Work Order ID 61935 Page 1 Friday, September 10, 2010 9:14:47 Item ID: D4172-043 Accept Setup Start **Revision ID: PRELIM** Item Name: Stop Z-Shape Section Assembly, LH **Start Date:** 9/10/2010 Start Qty: 1.00 **Cust Item ID:** Required Date: 9/17/2010 Req'd Qty: 1.00 **Customer:** Reference: Start Run Date: 10-9-12 Tooling: Approvals: Date: Stop QC: Date: SPC (Y/N): Date: Sequence ID/ **Operation** Tool # Plan Set Up/ Tool ID Accept Reject Reject Insp. Work Center ID Description **Run Hours** Code Oty Oty Number Stamp **Revision Nbr** Draw Nbr PA2 D4172 10.09.16 100 0.00 10-09-21 Small Fab 0.00 Memo Small Fab 1- Transfer drill holes, deburr and assemble as per dwg 110 QC5- Inspect part completeness to step on W/O Memo Quality Control

120

1

Identify as per dwg & Stock Location:

رس_{لان} 0.00

eation:

Packaging

Memo

0.00

ZT 10-09-21

Packaging

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES												
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector							
100922	(coo	rivets along angled top piece installed facing outward non permanent change ACCEPTABLE 120.04.72	8	(0 =972	l	cc.04,ZZ	10/08/22							

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
	Resolution:	Disposition:	QA: N/C Closed:	Date:

NCR:		V	VORK OR	DER NON-CONFORMANC	E (NCR)			
		Description of NC		Corrective Action Section B		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	QC Inspector
10-02-22	سمونا	3 rivets souted		(empre or ce install 3 news of vertex 3243 4-04 m 104291	100/22			
			,	what		:		
								_

NOTE: Date & initial all entries

Work Order ID 61935

Friday, September 10, 2010 9:14:47 AM



Page 2

Item ID:

D4172-043

PRELIM

Revision ID: Item Name:

Z-Shape Section Assembly, LH

Start Date:

9/10/2010

Start Qty: 1.00

Required Date: 9/17/2010

Req'd Qty: 1.00



Date:_____

Accept



Setup Start



Cust Item ID:

Customer:

Tool ID

Reference:

Approvals:

Process Plan:

QC:

Operation

Description

Date:_____

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Tool # Plan

Code

Reject

Qty

Start



Stop

Sequence ID/

Work Center ID

130

Quality Control

Memo

QC21- Final Inspection - Work Order Release

0.00

0.00

Run

Accept

Qty

Reject

Insp. Stamp

Number

POSITIVE RECALL

Dart Aerospace I	Ltd
------------------	-----

W/O:			WORK ORDER	CHANGES					
DATE	STEP	PR	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
								•	
Part No	:	PAR #:	Fault Category:	NCR: Ye	s No DQ	A:	Date: _		
	Resolution	າ:	Disposition:	QA: N/C	Closed:		Date: _		

NCR:		·	WORK ORDE	ER NON-CONFORMAN	CE (NCR)							
		Description of NC		Corrective Action Section B	3	Verification	Approval	Approval				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector				
						:						

NOTE: Date & initial all entries

Picklist Print

Friday, September 10, 2010 9:14:52 AM

Work Order ID: 61935

Parent Item: D4172-043

Parent Item Name: Z-Shape Section Assembly, LH

f

Start Date: 9/10/2010

Required Date: 9/17/2010

Start Qty: 1.00

Required Qty: 1.00

$\overline{}$				
n	m	m	ıts	•

IPP Rev:A 10.09.09 new issue DD verf:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Locatio	n	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4172-1		Manufactured	No				BE183	Each	0.0000		1	(0	~0°1	-21
D4172-3		Manufactured	No				100	Each	0.0000		1 -2-	т (0 - 09	1-21
D4172- 4 5 6-5 COV	owy DURZ	Manufactured	No				B (19	(939 Each	0.0000		1	<u>y</u> (0 - 0	9 - 2
Pivet	11 11 11 11 11 11 11 11 11 11 11 11 11	Purchased	No			B	100	Each	0.0000	46	46	۲ (0-0	۹ -2 ۱
MS20426AD3-\5		Purchased	No				100	Each Fw41	6,540.000 H	22	22 R -	<u> </u>	। -७९	<u>-3</u> \
MS21075L4 CL M S2	1025L4N bi	s.04.2(Location ST316	7 <u>1043</u> 74 110398			6540 2540 4000	Loc Code	- - -	123	- -		
MS21075L4 CL 132	****** *** ****	Purchased	No				100 (\S	Each 708	0.0000	11	11 	<u> </u>) - ७ ९	-21

M/

M



Nutplate

Dart Aerospace Ltd

W/O:			WORK ORDER (CHANGES										
DATE	STEP	PI	ROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector						
Part No	:	PAR #:	Fault Category:	NCR: Yes	s No DQ	A:	Date: _							
	Resolution	າ:	Disposition:	QA: N/C	Closed:		Date: _							

NCR:			WORK ORDE	R NON-CONFORMANC	E (NCR)							
	,	Description of NC		Corrective Action Section B	Verification	Ammunuml	Ammerical					
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector				
						:						
NOTE: D	 ate & initial al	Il entries						1				



